



Thru Tubing Solutions  
11515 S. Portland  
Oklahoma City, OK 73170  
(405) 692-1900  
[www.thrutubing.com](http://www.thrutubing.com)

**Thru Tubing Solutions' Abrasive Cutting System Performs Cut on Damaged 5.50" OD Casing, Creating a Cost Effective Solution to a Normally Very Costly Dilemma.**

**DETAILS:**

**Location:** Pecos County, TX

**Cut Depth:** 5,094 Feet

**Tools Ran:**  
1.70" OD Motor Head Assembly  
1.70" OD Hydraulic Disconnect  
1.70" OD TITAN Motor  
2.00" OD Abrasive Cutting Head

**Fluid:** Gelled Water

**Conveyance:** 1 1/4" Coiled Tubing

**OBJECTIVE:**

To cut 5.50" OD, 17# casing that had become shattered during a frac stimulation.

**RESULTS:**

In 40 minutes pumping at 1 BPM the casing had been completely cut, allowing rig to pull casing out of the hole and latch back onto lower section of casing with new casing.

**VALUE TO CLIENT:**

Damaged casing was cleanly removed. This expedited the re-completion of the well, avoiding costly and lengthy fishing of the damaged casing.

